

Sandwich West Parkway Roundabout Construction

LaSalle 25 Eastbound and Westbound

7/22/2025
3:27 PM

Legend

- LaSalle 25
- Detour Route
- ✕ No Service on Regular Route
- Regular Bus Stop
- Closed Bus Stop

Detour Notes


Start Date: July 28, 2025

Approximate End Date: End of October 2025

Eastbound and Westbound:

The construction of a roundabout at the Sandwich Parkway at Heritage Drive intersection will cause a detour for both directions of the LaSalle 25 route.

Transit Windsor cannot drop off or pick up passengers in construction zones.



Bus stops that are temporarily closed and moved to a new location for the duration of this project are as follows:

Bus Stop Closed	Direction	Temporary Location	Direction
Eastbound LaSalle 25			
Sandwich West at D'Amore (Stop ID 772225)	S/E Corner	Sandwich at Mary (Existing Stop, Stop ID 772224)	S/E Corner
Sandwich West at Durocher (Stop ID 772226)	S/W Corner	Sandwich at Mary (Existing Stop, Stop ID 772224)	S/E Corner
Sandwich West at Lovell (Stop ID 772227)	S/E Corner	Sandwich at Mary (Existing Stop, Stop ID 772224)	S/E Corner
Heritage at Sandwich West (Stop ID 772228)	S/W Corner	Heritage at Rushwood (Existing Stop, Stop ID 772230)	S/W Corner
Heritage at Rushwood (Stop ID 772229)	N/W Corner	Heritage at Rushwood (Existing Stop, Stop ID 772230)	S/W Corner

Bus Stop Closed	Direction	Temporary Location	Direction
Westbound LaSalle 25			
Heritage at Rushwood (Stop ID 772146)	N/E Corner	Heritage at Rushwood (Existing Stop, Stop ID 772145)	S/E Corner
Heritage at Sandwich West (Stop ID 772147)	S/E Corner	Heritage at Rushwood (Existing Stop, Stop ID 772145)	S/E Corner
Sandwich West at Lovell (Stop ID 772148)	N/E Corner	Sandwich at Mary (Existing Stop, Stop ID 772151)	N/E Corner
Sandwich West at Durocher (Stop ID 772149)	N/E Corner	Sandwich at Mary (Existing Stop, Stop ID 772151)	N/E Corner
Sandwich West at D'Amore (Stop ID 772150)	N/E Corner	Sandwich at Mary (Existing Stop, Stop ID 772151)	N/E Corner